

TECH TIPS



PART NUMBERS AFFECTED: A14396, A14797,
A14875, A14970, A14972

MANUFACTURER: VOLKSWAGEN

YEAR: 1985-1990

CONDITION:

1985-1990 VOLKSWAGEN GOLFS, JETTAS, AND PASSATS WHICH ARE EQUIPPED WITH GAS ENGINES MAY BE SUBJECT TO A LOW ALTERNATOR OUTPUT, ALTERNATOR LIGHT “ ON ” (DASH), AND/ OR SQUEALING BELTS WHEN DRIVEN IN WET CONDITIONS.

SOLUTION:

VOLKSWAGEN HAS DEVELOPPED SPLASH SHIELDS TO CORRECT THIS PROBLEM:

- PART # 191 025 001C FOR VOLKSWAGEN GOLFS AND JETTAS
- PART # 357 825 254 FOR VOLKSWAGEN PASSATS

THESE SHIELDS ARE INSTALLED OVER THE DRIVE BELTS, IN ORDER TO PROTECT THEM FROM MOISTURE AND ALSO PREVENTS THE BELTS FROM SLIPPING WHICH WOULD CAUSE THE LOW ALTERNATOR OUTPUT.